

CARDIAC TROPONIN PANEL # MDXPCT- 001

0.5 ml Matched Serum, K2 EDTA Plasma, and Li Heparin Plasma

ID #	Age	Gender	Ethnicity	Race	Smoker/Non- Smoker	Cause of elevated Troponin	Symptoms	Date of Event	Admitted AM/PM
7001	64	Male	Hispanic	Caucasian	Smoker	Heart Attack	Chest pain, left arm pain, Diaphorisis	3/28/2019	РМ

Sample ID	Draw	Time Point	BP	Draw Date	Troponin	Myoglobin	Matrix
A11703150	1	12-18 HRS	190/120	3/29/2019	38.0 ng/mL	15.0 ng/mL	SERUM
A11703151	1	12-18 HRS	190/120	3/29/2019	Not Tested	Not Tested	K2 EDTA
A11703152	1	12-18 HRS	190/120	3/29/2019	Not Tested	Not Tested	LIH
A11703156	2	24 HRS POST	182/110	3/30/2019	34.2 ng/mL	10.1 ng/mL	SERUM
A11703157	2	24 HRS POST	182/110	3/30/2019	Not Tested	Not Tested	K2 EDTA
A11703158	2	24 HRS POST	182/110	3/30/2019	Not Tested	Not Tested	LIH
A11703165	3	48 HRS POST	180/112	3/31/2019	26.0 ng/mL	9.4 ng/mL	SERUM
A11703166	3	48 HRS POST	180/112	3/31/2019	Not Tested	Not Tested	K2 EDTA
A11703167	3	48 HRS POST	180/112	3/31/2019	Not Tested	Not Tested	LIH
A11703177	4	72 HRS POST	170/104	4/1/2019	24.0 ng/mL	4.5 ng/mL	SERUM
A11703178	4	72 HRS POST	170/104	4/1/2019	Not Tested	Not Tested	K2 EDTA
A11703179	4	72 HRS POST	170/104	4/1/2019	Not Tested	Not Tested	LIH

Troponin Testing was performed on Tosoh AIA-360/Myoglobin Testing was performed on RayBio Human Myoglobin ELISA Kit

CAUTION: HUMAN BLOOD

All materials listed above are considered to be potentially infectious and should be handled with universal precautions.

MRN Diagnostics * 101 Constitution Blvd., Suite G * Franklin, MA 02038 * P:508-384-0033