



CARDIAC TROPONIN PANEL # MDXPCT- 008

0.5 ml Matched Serum, K2 EDTA Plasma, and Li Heparin Plasma

ID #	Age	Gender	Ethnicity	Race	Smoker/Non-Smoker	Cause of elevated Troponin	Symptoms	Date of Event	Admitted AM/PM
7012	76	Male	Hispanic	Caucasian	Smoker	Heart Attack	Chest pain, left arm pain, Shortness of Breath	4/11/2019	AM

Sample ID	Draw	Time Point	BP	Draw Date	Troponin	Myoglobin	Matrix
A11703249	1	12-18 HRS	160/90	4/12/2019	44.0 ng/mL	>200 ng/mL	SERUM
A11703250	1	12-18 HRS	160/90	4/12/2019	Not Tested	Not Tested	K2 EDTA
A11703251	1	12-18 HRS	160/90	4/12/2019	Not Tested	Not Tested	LIH
A11703258	2	24 HRS POST	152/82	4/13/2019	38.2 ng/mL	>200 ng/mL	SERUM
A11703259	2	24 HRS POST	152/82	4/13/2019	Not Tested	Not Tested	K2 EDTA
A11703260	2	24 HRS POST	152/82	4/13/2019	Not Tested	Not Tested	LIH
A11703267	3	48 HRS POST	140/80	4/14/2019	34.4 ng/mL	123.1 ng/mL	SERUM
A11703268	3	48 HRS POST	140/80	4/14/2019	Not Tested	Not Tested	K2 EDTA
A11703269	3	48 HRS POST	140/80	4/14/2019	Not Tested	Not Tested	LIH
A11703276	4	72 HRS POST	140/80	4/15/2019	20.2 ng/mL	97.0 ng/mL	SERUM
A11703277	4	72 HRS POST	140/80	4/15/2019	Not Tested	Not Tested	K2 EDTA
A11703278	4	72 HRS POST	140/80	4/15/2019	Not Tested	Not Tested	LIH

Troponin Testing was performed on Tosoh AIA-360/Myoglobin Testing was performed on RayBio Human Myoglobin ELISA Kit

CAUTION: HUMAN BLOOD

All materials listed above are considered to be potentially infectious and should be handled with universal precautions.