



CARDIAC TROPONIN PANEL # MDXPCT- 002
0.5 ml Matched Serum, K2 EDTA Plasma, and Li Heparin Plasma

ID #	Age	Gender	Ethnicity	Race	Smoker/Non-Smoker	Cause of elevated Troponin	Symptoms	Date of Event	Admitted AM/PM
7002	50	Male	Hispanic	African	Smoker	Heart Attack	Chest pain, left arm numbness, Diaphoresis	3/28/2019	AM

Sample ID	Draw	Time Point	BP	Draw Date	Troponin	Myoglobin	Matrix
A11703153	1	12-18 HRS	168/96	3/29/2019	40.0 ng/mL	4.8 ng/mL	SERUM
A11703154	1	12-18 HRS	168/96	3/29/2019	Not Tested	Not Tested	K2 EDTA
A11703155	1	12-18 HRS	168/96	3/29/2019	Not Tested	Not Tested	LIH
A11703159	2	24 HRS POST	150/90	3/30/2019	38.2 ng/mL	10.5 ng/mL	SERUM
A11703160	2	24 HRS POST	150/90	3/30/2019	Not Tested	Not Tested	K2 EDTA
A11703161	2	24 HRS POST	150/90	3/30/2019	Not Tested	Not Tested	LIH
A11703168	3	48 HRS POST	140/90	3/31/2019	34.0 ng/mL	7.7 ng/mL	SERUM
A11703169	3	48 HRS POST	140/90	3/31/2019	Not Tested	Not Tested	K2 EDTA
A11703170	3	48 HRS POST	140/90	3/31/2019	Not Tested	Not Tested	LIH
A11703180	4	72 HRS POST	140/84	4/1/2019	28.2 ng/mL	7.0 ng/mL	SERUM
A11703181	4	72 HRS POST	140/84	4/1/2019	Not Tested	Not Tested	K2 EDTA
A11703182	4	72 HRS POST	140/84	4/1/2019	Not Tested	Not Tested	LIH

Troponin Testing was performed on Tosoh AIA-360/Myoglobin Testing was performed on RayBio Human Myoglobin ELISA Kit

CAUTION: HUMAN BLOOD

All materials listed above are considered to be potentially infectious and should be handled with universal precautions.